

RABIGH PP Stage-V 380Kv Site Photos

380KV Power Cable (1 c x 800mm² XLPE Cu Cable)



Tre foil Cleat Clamp for 380kV Power Cable



UPN SUPPORTS INSTALLATION



Positioning of 380kV Power Cable at Site



Positioning the Power cable in the Ladder support



Arrangement of Power cable in the UPN Support after laying



Cable marking and taping of Power Cable before cutting



Exposure of Power cable conductor



Waterproofing and application of Epoxy putty



Assembled Transformer SE ready for insertion



Link Box Testing



TESTING AND COMMISSIONING WORKS FOR 380KV



Connection set up in the Test Bushing for Transformer

